


???????? CZKPJ H60



????????:

???????? ??? ????????? CZKPJ H60 ??? ????????? ?????? BAKS ?????? 60??

????????

???????? ????????? ????.

????????

????, ????????? ?????? ?????????.

?? ?????????:

L - ????????? ????????? ???-???? ???????

F - ?????, ????????? ?????? ?????????

E - ????????? ?????

?? ?????? ??? ?????????????????? ????? SGK M6×10 ?? SG M6×10.

?????	???????????? ?????	????? a [??]	???? [??]	???????? ? ????????? [??]
CZKPJ50H60	164924	50	0,66	20
CZKPJ100H60	164314	100	1,23	20
CZKPJ150H60	164414	150	1,58	10
CZKPJ200H60	164514	200	1,98	10
CZKPJ300H60	164614	300	2,88	10
CZKPJ400H60	164714	400	3,94	10
CZKPJ500H60	164814	500	5,16	10
CZKPJ600H60	164914	600	6,53	10

